

FIG. 1A




FIG. 1B




FIG.2A




FIG.2B




FIG. 4




FIG.5A




FIG.5B

FIG. 7







FIG. 6



TRANSMITTED SIGNALS

RECEIVED SIGNALS






FIG. 8



TRANSMITTER 902

FIG. 9




FIG. 10A




FIG. 11A




FIG. 12






FIG. 13

FIG. 14

1404
2



1402
2






FIG 15

NOT TO BE REPRODUCED WITHOUT PERMISSION
OF THE U.S. GOVERNMENT




FIG 16A

NY
Kendall County, Illinois









FIG 16B










FIG 21




FIG 22






FIG 23








FIG 26


FRAME 1

FRAME 2

FRAME 3

FRAME 4

27024 ~



2704A ~





FIG 27A

2702B ~



2704B ~




FIG 27B




FIG 28

RECEIVER 2902 2








FIG. 29








FIG. 31




FIG. 32




FIG. 33A

FIG. 33B